









8122















8122N


NR	ELEMENT	8122N
E1		1
E2		1
E3		1
E4		2
E5		1



8122N

Nr	Element	DIN	ELEMENT	Σ
1		-	S6x60	2
2		-	W6x60	1
21		DIN 125	8x16	1
58		-	LOCTITE	1
77		-	K3_d30_A89_G	1
90		DIN 125	16x30	4
164		DIN 985	M16	2
213		-	Z_NA_1	1
214		-	Z_NA_2	1
229		-	Z_R_42	4
230		-	S1_8100_0	2
231		-	S2_8100_0	2



8122N



# 8122N



ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”




1

8122N




2

8122N




INST\_81\_0\_1





3

8122N



INST\_81\_17








4

8122N

B25 0,4m<sup>3</sup>



min. 48H



5

8122N

